

AD-A104 828

PRC CONSOER TOWNSEND INC ST LOUIS MO

F/G 13/13

NATIONAL DAM SAFETY PROGRAM. MEMPHIS RESERVOIR DAM (MO 10163) M--ETC(U)  
JAN 79 DACW43-78-C-0160

DACW43-78-C-0160

NL

UNCLASSIFIED

2

5-24-20

**LEVEL**



**MISSISSIPPI - SALT - QUINCY RIVER BASIN**

*Handwritten mark*


**AD A104828**

**MEMPHIS RESERVOIR DAM  
SCOTLAND COUNTY, MISSOURI  
MO 10163**

**DTIC  
ELECTE  
SEP 30 1981**

**PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM**

**DTIC FILE COPY**



THIS DOCUMENT IS BEST QUALITY PRACTICABLE.  
THE COPY FURNISHED TO DDC CONTAINED A  
SIGNIFICANT NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.

**PREPARED BY: U. S. ARMY ENGINEER DISTRICT, ST. LOUIS**

**FOR: STATE OF MISSOURI**

**81 9 28 093**

**JANUARY 1979**

**DISTRIBUTION STATEMENT A**

**Approved for public release;  
Distribution Unlimited**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. <b>AD-A104</b>	3. RECIPIENT'S CATALOG NUMBER <b>828</b>
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Memphis Reservoir Dam (MO 10163) Scotland County, Missouri		5. TYPE OF REPORT & PERIOD COVERED <b>Final Report</b>
7. AUTHOR(s) Consoer, Townsend and Associates, Ltd.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s) <b>DACW43-78-C-0160</b>
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) <b>10163</b>		12. REPORT DATE <b>January 1979</b>
		13. NUMBER OF PAGES <b>Approximately 70</b>
		15. SECURITY CLASS. (of this report) <b>UNCLASSIFIED</b>
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  Approved for release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)  National Dam Safety Program. Memphis Reservoir Dam (MO 10163) Mississippi - Salt - Quincy River Basin, Scotland County, Missouri. Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)  Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

412.553

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DTIC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**



DEPARTMENT OF THE ARMY  
ST. LOUIS DISTRICT, CORPS OF ENGINEERS  
210 NORTH 12TH STREET  
ST. LOUIS, MISSOURI 63101

IN REPLY REFER TO

SUBJECT: Memphis Reservoir Dam (Mo. 10163),  
Phase I Inspection Report

This report presents the results of field inspection and evaluation of Memphis Reservoir Dam (Mo. 10372). It was prepared under the National Program of Inspection of Non-Federal Dams.

SUBMITTED BY:

SIGNED

Chief, Engineering Division

1 MAR 1975  
(Date)

APPROVED BY:

SIGNED

Colonel, CE, District Engineer

1 MAR 1979  
(Date)

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A23	

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Memphis Reservoir Dam, Missouri Inv. No. 10163  
State Located: Missouri  
County Located: Scotland  
Stream: Unnamed Tributary of the North Fabius River  
Date of Inspection: October 4, 1978

Memphis Reservoir Dam No. Mo.10163 was inspected using the "Recommended Guidelines for Safety Inspection of Dams". These guidelines were developed by the Chief of Engineers, U.S. Army, Washington, D.C., with the help of Federal and state agencies, professional engineering organizations, and private engineers. The resulting guidelines are considered to represent a consensus of the engineering profession.

Based on the criteria in the guidelines, the dam is in the high hazard potential classification, which means that loss of life and appreciable property loss could occur in the event of failure of the dam. Three houses, the Scotland County Fairgrounds, several farm buildings, and a State Highway crossing would be subjected to flooding, with possible damage and/or destruction, and possible loss of life. Memphis Reservoir Dam is in the small size classification since it is less than 40 feet high and impounds less than 1,000 acre-feet of water.

Our inspection and evaluation indicates that the spillway of Memphis Reservoir Dam does not meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. Memphis Reservoir Dam is a small size dam with a high hazard potential required by the guidelines to pass the Probable Maximum Flood without overtopping. Since there is a significant development downstream of the dam, the Probable Maximum flood is the appropriate spillway design flood. It was determined that the spillway will pass 25 percent of the Probable Maximum Flood without overtopping the dam. Also, our evaluation indicates that the spillway will pass the 100-year flood; that is, a flood having a 1 percent chance of being equalled or exceeded during any given year.

The Probable Maximum Flood is defined as the flood discharge that may be expected from the most severe combination of critical meteorological and hydrologic conditions that are reasonably possible in the region.

Other deficiencies noted by the inspection team were a need for an periodic inspection by a qualified professional engineer; the lack of a maintenance schedule; small trees and brush on the upstream embankment slope; vegetation in the approach channel of the spillway; and eroded and spalled concrete on the spillway structure. The lack of stability and seepage analysis on record is also a deficiency that should be corrected.

It is recommended that the owner take action to correct or control the deficiencies described above.



MEMPHIS RESERVOIR DAM



PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Memphis Reservoir Dam, I.D. No. 10163

TABLE OF CONTENTS

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 1	PROJECT INFORMATION . . . . .	1
	1.1 General . . . . .	1
	1.2 Description of Project . . . . .	3
	1.3 Pertinent Data . . . . .	7
SECTION 2	ENGINEERING DATA . . . . .	13
	2.1 Design . . . . .	13
	2.2 Construction . . . . .	13
	2.3 Operation . . . . .	13
	2.4 Evaluation . . . . .	14
SECTION 3	VISUAL INSPECTION . . . . .	16
	3.1 Findings . . . . .	16
	3.2 Evaluation . . . . .	19
SECTION 4	OPERATION PROECEDURES . . . . .	20
	4.1 Procedures . . . . .	20
	4.2 Maintenance of Dam . . . . .	20
	4.3 Maintenance of Operating Facilities . . . . .	20
	4.4 Description of Any Warning System in Effect . . . . .	21
	4.5 Evaluation . . . . .	21
SECTION 5	HYDRAULIC/HYDROLOGIC . . . . .	22
	5.1 Evaluation of Features . . . . .	22

TABLE OF CONTENTS  
(Continued)

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 6	STRUCTURAL STABILITY . . . . .	26
	6.1 Evaluation of Structural Stability . . . . .	26
SECTION 7	ASSESSMENT/REMEDIAL MEASURES . . . . .	28
	7.1 Dam Assessment . . . . .	28
	7.2 Remedial Measures . . . . .	30

LIST OF PLATES

	<u>Plate No.</u>
LOCATION MAP . . . . .	1
ELEVATION OF SPILLWAY CRESTS . . . . .	2-3
GENERAL GEOLOGIC MAP . . . . .	4

APPENDICES

APPENDIX A	-	PHOTOGRAPHS TAKEN DURING INSPECTION
APPENDIX B	-	HYDROLOGIC COMPUTATIONS

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

MEMPHIS RESERVOIR DAM, Missouri Inv. No. 10163

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

The Dam Inspection Act, Public Law 92-367 of August, 1972, authorizes the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspections. Inspection for the Memphis Reservoir Dam was carried out under Contract DACW 43-78-C-0160 to the Department of the Army, St. Louis District, Corps of Engineers, by the engineering firms of Consoer, Townsend & Associates Ltd., and Engineering Consultants, Inc. (A Joint Venture), of St. Louis, Missouri.

b. Purpose of Inspection

The visual inspection of the Memphis Reservoir Dam was made on September 28, and October 4, 1978. The purpose of the inspection was to make a general assessment as to the structural integrity and operational adequacy of the dam embankment and its appurtenant structures.

c. Scope of Report

This report summarizes available pertinent data relating to the project; presents a summary of visual observations made during the field inspection; presents an evaluation of hydrologic and hydraulic conditions at the site; presents an evaluation as to the structural adequacy of the various project features; and assesses the general condition of the dam with respect to safety.

It should be noted that reference in this report to left or right abutments is as viewed looking downstream. Where left abutment or left side of the dam is used in this report, this also refers to north abutment or side, and right to the south abutment or side.

d. Evaluation Criteria

Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams", Appendix D. These guidelines were developed with the help of several Federal agencies and many state agencies, professional engineering organizations, and private engineers.

## 1.2 Description of the Project

### a. Description of Dam and Appurtenances

The dam embankment is a homogeneous earthfill structure. The crest of the embankment has a width of 20 feet and a length of approximately 854 feet. The crest has a minimum elevation of 720.2 feet above MSL, and the maximum height of the embankment is 28.2 feet above the minimum streambed elevation along the centerline of the dam.

The upstream slope of the embankment section is constructed with a 1V to 2H slope, and the downstream embankment slope is 1V to 1-3/4H. A thin layer of rock riprap is provided on the upstream slope from the crest to approximately elevation 715.0. The riprap is composed of angular blocks of limestone up to 2 feet in diameter with the majority of the blocks 6 inches to 1 foot in diameter. The crest and downstream embankment slopes are protected with a vegetative cover.

Bedrock at the site and within the vicinity is composed of Pennsylvanian age limestone and minor amounts of sandstones and shales. No bedrock crops out over the site, but the rolling hills are mantled with a residual clay, a weathered product of the bedrock. The site is adjacent to the floodplain of the North Fabius River, thus, alluvial deposits of unknown thickness are expected in the relatively broad valley at this site.

The abutments and spillways for the dam are founded in the residual clays. The embankment across the valley has been placed upon alluvial sediments.

Available design drawings do not indicate the type of foundation treatment undertaken prior to fill placement.

There are three spillways for the Memphis Reservoir. The service spillway, which is the oldest among the three spillways, is located on the right abutment of the embankment. This spillway consists of an uncontrolled concrete weir section, a spillway chute, a stilling basin with baffle blocks, and an exit channel. Spillway No. 2, which was also part of the original construction, is connected to the right entrance wall of the service spillway crest structure. This spillway was rebuilt in 1958, due to severe concrete cracking and failure of the original spillway crest. The present spillway crest is a new concrete wall containing seven weir openings. The spillway chute and exit channel remain the same as the original construction.

The emergency spillway is located at approximately 300 feet south of the dam embankment at the southeast corner of the reservoir. The emergency spillway is a grass lined open channel which runs easterly for about 150 feet, then turns north into the natural channel.

Structural dimensions of these spillway are given in Section 1.3, Appendix D, and in the plates in this report.

Up to the time of this report, design data with an adequate description of the submerged and underground features of the outlet works and pumping plant was not available. The description herein, therefore, is derived wholly from the visual inspection observations.

An intake tower approximately 4 feet square and constructed of concrete is situated in the reservoir about 40 feet upstream of the dam crest. Access to the tower is provided by two parallel steel I-beams, spanning from the dam crest to the tower, to which a walkway of wood planks is bolted.

A pump vault lies at the downstream toe of the dam opposite the intake tower. The vault contains two horizontally mounted centrifugal pumps with 4-inch discharge pipes connected in parallel to a 6-inch discharge line. The pump suctions connect to a 6-inch pipe which, presumably, passes under the dam embankment to connect to the intake tower.

The water surface elevation was about 1 inch below the service spillway crest at the time of inspection.

The reservoir rim is generally gentle sloping, with a city park area at the left shore and trees, grass and brush at the right shore.

b. Location

The Memphis Reservoir Dam is located on an unnamed tributary of the North Fabius River, Scotland County, Missouri. The reservoir is also located just downstream from the Memphis Lake and Park Dam, which was built in 1974. The nearest downstream community is Memphis, Missouri, which is roughly 2 miles from the dam. The dam and reservoir are shown on the Memphis Quadrangle Sheet (7.5 minute series) in Section 14, Township 65 North, Range 12 West.

c. Size Classification

According to the "Recommended Guidelines for Safety Inspection of Dams", by the U.S. Department of the Army, Office of the Chief Engineer, the dam is classified in the dam height category as being "Small" since its storage is less than 1,000 acre-feet. The dam is also classified as "Small" in dam size category because its height is less than 40 feet. The overall size classification is, accordingly, "Small" in size.

d. Hazard Classification

The dam has been classified as having "High" hazard potential in the National Inventory of Dams, on the basis that in the event of failure of the dam or its appurtenances, excessive damage could occur to downstream property, together with the possibility of the loss of life. Our findings concur with the classification. The estimated damage zone extends two miles downstream of the dam. Within the damage zone are two to three houses, the Scotland County Fairgrounds, several farm buildings, and a State highway crossing. The floodplain is farmed.

e. Ownership

Memphis Reservoir Dam is owned by the City of Memphis, Missouri.



f. Purpose of Dam

The main purpose of the dam is to impound water for use as water supply for the City of Memphis, Missouri.

g. Design and Construction History

Memphis Reservoir Dam was constructed in 1931. In 1958, the new concrete spillway wall with the series of weir openings was constructed. This reconstruction was designed by Frank Beard, P.E., of Kahoka, Missouri. Raising of the dam was planned and designed in 1958, but the work was never done.

h. Normal Operational Procedures

The dam is used to impound water for recreational use and water supply. The water level is controlled by rainfall, runoff, evaporation, and discharges from the Memphis Lake and Park Dam (10217), which is located approximately one-half mile upstream. It is believed that the reservoir is kept as full as possible at all times.

1.3 Pertinent Data

Memphis Reservoir Dam

a. Drainage Area (acres):	947 (Excluding drainage area of Memphis Lake & Park Dam)
---------------------------	--

b. Discharge at Damsite

Estimated experienced maximum flood (cfs):	700
Estimated ungated spillway capacity at maximum pool elevation (cfs):	3,751

c. Elevation (Feet above MSL)

Top of dam:	720.2
Spillway crest:	
Spillway No. 1	716.2
Spillway No. 2	717.1
Emergency Spillway	717.7
Minimum streambed elevation at centerline of dam:	701.0
Maximum tailwater:	Unknown

d. Reservoir

Length of maximum pool (feet):	5,600
--------------------------------	-------

e. Storage (Acre-Feet)

Top of dam:	235
-------------	-----

f. Reservoir Surface (Acres)

Top of dam:	54
Spillway crest:	41

g. Dam

Type:	Earth embankment
Length:	854 feet
Height (maximum):	28.2 feet
Top width:	20 feet
Side slopes:	
Downstream	1V to 1-3/4H
Upstream	1V to 2H
Zoning:	None

Impervious core:	None
Cutoff:	Not known
Grout curtain:	None

h. Diversion and Regulating Tunnel	None
------------------------------------	------

i. Spillway

Type:	Uncontrolled
Length of weir (feet):	
Spillway No. 1	58
Spillway No. 2	57.19 feet
Emergency Spillway	75
Crest Elevation (feet above MSL):	
Spillway No. 1	716.2
Spillway No. 2	717.1
Emergency Spillway	717.7

j. Regulating Outlets

Type:	6-inch cast iron pipe
Length:	80 feet
Closure:	Gate valve at pump vault
Maximum Capacity:	Unknown

Memphis Lake and Park Dam

a. Drainage Area:	1,950 acres
-------------------	-------------

b. Discharge at Damsite:	All discharge at the dam-site is through two uncontrolled spillways with an 18-inch cast iron gate in the service spillway shaft, a low level outlet conduit, and a water supply system
--------------------------	---

Estimated experienced maximum flood: 0 cfs  
Estimated ungated spillway capacity  
at maximum pool elevation: 7,565 cfs

c. Elevation: (Feet above MSL)

Top of dam:	780.0
Spillway crest: (Service spillway)	770.0
(Emergency spillway)	774.0
Minimum streambed elevation at centerline of dam:	710.0
Maximum tailwater:	Unknown

d. Reservoir

Length of maximum pool: 8,600 feet ±

e. Storage: (Acre-Feet)

Top of dam (from 1974 inventory):	7,030
Spillway crest: (Service spillway)	5,164
(Emergency spillway)	4,109

f. Reservoir Surface: (Acres)

Top of dam (interpolated value):	342
Spillway crest:	248

g. Dam

Type:	Zoned earth embankment
Length:	1,635 feet
Height (maximum):	70 feet
Top width:	10 feet
Side slopes:	
(Downstream)	1V to 2-1/2H for top 20 feet 1V to 4H for next 16 feet 1V to 10H for next 4 feet 1V to 2-1/2H to ground surface
(Upstream)	Same

Zoning:	Three - core, shells and stabilization berms
Impervious core:	5-foot top width with 1V to 1H upstream slope and 3/4V to 1H downstream slope
Cutoff:	Core trench with 10-foot bottom width and 1V to 1H side slopes
Grout curtain:	None

h. Diversion Tunnel	None
---------------------	------

i. Spillway

Type:	(Service spillway)	Uncontrolled
	(Emergency spillway)	Uncontrolled
Length of weir:	(Service spillway)	25 feet
	(Emergency spillway)	250 feet
Crest elevation:	(Service spillway)	770 feet
	(Emergency spillway)	774 feet

j. Regulating Outlets

Type:	18-inch sluice gate discharging into service spillway conduit
Length:	350 feet
Closure:	18-inch sluice gate
Maximum capacity:	30 cfs

Type:	12-inch diameter ductile iron low level outlet pipe
Length:	420 feet
Closure:	Mud valve at upstream end and gate valve at downstream end
Maximum capacity:	+ 25 cfs

Type:	12-inch diameter ductile iron water supply outlet
Length:	Unknown

Closure:

Gate valve at upstream end

Maximum capacity:

Unknown

## SECTION 2: ENGINEERING DATA

### 2.1 Design

The available design drawings are very incomplete. No drawings of the original construction were found, and the only drawings located were of proposed reconstruction in 1958, most of which was not constructed. These drawings partially show the existing structures at that time.

### 2.2 Construction

The dam was originally constructed in 1931. In 1958, a new spillway wall for spillway No. 2 was constructed upstream of the existing wall which ran in a north-south direction.

### 2.3 Operation

No operation records for Memphis Reservoir Dam are available.

## 2.4

### Evaluation

#### a. Availability

The only engineering data available are drawings made in 1958 showing proposed reconstruction, most of which was not constructed. These drawings partially show the existing dam at that time. No design computations, construction data, or operation data is available.

In addition, no pertinent data was available for review of hydrology spillway capacity, flood routing through the reservoir, outlet capacity, slope stability, seepage analysis, or foundation conditions.

#### b. Adequacy

The engineering data available is inadequate to aid in evaluating the hydraulic and hydrologic capabilities and stability of the dam for Phase I investigations.

The lack of engineering data did not allow for a definitive review and evaluation. Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing and evaluating design, operation and construction data, but is based primarily on visual inspection, past performance history, and sound engineering judgment.

Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.



c. Validity

No valid engineering data is available.

### SECTION 3: VISUAL INSPECTION

#### 3.1 Findings

##### a. General

A visual inspection of Memphis Reservoir Dam was made on September 28, and October 4, 1978. The following persons were present during the inspection:

<u>Name</u>	<u>Affiliation</u>	<u>Disciplines</u>
Yin Au-Yeung	Engineering Consultants, Inc.	Project Engineer, Hydraulics and Hydrology
David Bramwell	Engineering Consultants, Inc.	Geology
Jon Diebel	Engineering Consultants, Inc.	Soils
John Ismert	Engineering Consultants, Inc.	Mechanical
Kevin Blume	Consoer, Townsend & Assoc., Ltd.	Civil & Structural

Specific observations are discussed below.

##### b. Dam

The crest of the dam is adequately protected by vegetative cover. The crest makes a nearly 90 degree bend to the west at the left side of the dam.

The upstream embankment slope is protected with a 1 to 2 foot thick layer of dumped riprap. The riprap is composed of angular blocks of limestone up to 2 feet thick, with most of the blocks having a size between 6 inches and 1 foot. The riprap extends from a point several feet from the

top of the crest on below elevation 716.2 for an unknown depth. Some large brush and small trees are beginning to grow on the upstream slope of the embankment, but not to an extensive degree at this time. Sloughing and erosion was not prevalent on the slope at this time.

The downstream embankment slope is protected by a vegetative cover. The vegetation had been recently cleared prior to the inspection. Some stumps of trees which had been previously cut were observed. No signs of past or present instability were seen on the embankment or in the foundation at any location. Also, no seepage was observed on the downstream embankment slope or downstream of the toe of the dam.

c. Appurtenant Structures

(1) Spillway

Mostly due to the old age of the structure, the service spillway shows signs of deterioration. Some leakage is occurring through the vertical concrete weir. In addition, vertical and horizontal cracking, and concrete spalling and erosion was observed throughout the concrete channel. Dense grasses are growing in the spillway approach areas.

Spillway No. 2, which is relatively new, is in adequate condition. Only minor cracks in the weir structure were observed.

The emergency spillway is well-defined and adequately protected by thick grass.

All three spillways merge into the natural channel approximately 70 feet downstream of the embankment toe.

(2) Outlet Works

Inspection was made of the unsubmerged portion of the intake tower. The concrete which could be observed was old, but in satisfactory condition. The top of the tower is covered by a steel sheet cover which could not be removed. A heavy wire screen mounted to a crude wooden frame was suspended over the face of one side of the tower; presumably this is a trash screen over the intake opening.

The cover of the pump vault was removed and the vault was entered for inspection. The appearance of the pumping and piping equipment was satisfactory, except there was several inches of standing water over the vault floor, and the electrical control boxes were open and the exposed wiring was in disarray. It was obvious from the condition of the wiring that the pumps were not operational.

d. Reservoir Area

No wave wash, excessive erosion, or slope slides were observed along the shore of the reservoir. At present, no development has occurred along the shoreline. In general, the reservoir rim is stable. Most of the inflow into the reservoir is controlled by releases from the Memphis Lake and Park Dam, which is located about one-half mile upstream from Memphis Reservoir.

e. Downstream Channel

Spillway discharge from all the spillways merge into the natural channel at approximately 70 feet downstream of the embankment toe. The downstream channel is an unlined trapezoidal channel which was sparsely covered with fallen tree trunks and debris at the time of inspection. However, this minor obstruction in the channel does not seem to pose serious restrictions to the spillway capacity. Signs of moderate erosion and sloughing on the right bank of the channel were observed.

3.2 Evaluation

The visual inspection did not exhibit any items which are sufficiently significant to indicate a need for immediate remedial action.

The following deficiencies were observed which could affect the safety of the dam, or which will require maintenance within a reasonable period of time.

1. The trees and brush beginning to grow on the upstream embankment slope.
2. The vegetation growing in the approach channel for the service spillway and the slotted spillway.
3. The deteriorated concrete and leakage observed in the concrete channel of the service spillway.

## SECTION 4: OPERATIONAL PROCEDURES

### 4.1 Procedures

Normal procedure is to allow the reservoir to stay close to full at all times. Should the water level drop below acceptable levels, water is released from the Memphis Lake and Park Dam (MO 10217), and allowed to flow along the natural streambed to the reservoir downstream. Basically, the water level is controlled by rainfall, runoff, evaporation, and water consumption of the city of Memphis, Missouri.

### 4.2 Maintenance of Dam

Maintenance is performed at the damsite by workers employed by the city of Memphis, Missouri. At the time of inspection, it was apparent that all trees and brush had been recently cleared from the downstream embankment slope. Small trees are growing on the upstream slope, and should also be removed. Observation of the small pump vault located at the downstream toe, opposite the intake tower, showed the pumps to be inoperable. The inspection team was not aware of any available maintenance or water level records.

### 4.3 Maintenance of Operating Facilities

The only operating facility at the damsite is the small water supply pump vault located at the downstream toe opposite the 3-foot square concrete intake tower. The small vault contains two horizontally mounted centrifugal pumps with 4-inch discharge pipes

connected in parallel to a 6-inch discharge line. The appearance of the pumping and piping equipment in the vault was satisfactory, except there was several inches of standing water over the vault floor and the electrical control boxes were open, with the exposed wiring in disarray. It was obvious from the condition of the wiring that the pumps were not operational, due to a lack of maintenance.

#### 4.4 Description of Any Existing Warning System

The inspection team is not aware of any existing warning system in effect.

#### 4.5 Evaluation

The maintenance and operation at the damsite is fair. The clearing of the upstream slope should be done within a reasonable period of time, and the access to the pump vault should be made secure and kept locked for public safety. Other items requiring maintenance are discussed in Section 3.2.

## SECTION 5: HYDRAULIC/HYDROLOGIC

### 5.1 Evaluation of Features

#### a. Design

No hydrologic design data is available.

The watershed area of Memphis Reservoir is roughly 2,899 acres, which includes the New Memphis Lake and its watershed area of + 1,950 acres. This area is approximately 5 percent covered with brush and forest. Land gradients average about 4 percent. The Memphis Reservoir is located just downstream of the New Memphis Lake, on an unnamed tributary of the North Fabius River. The Memphis Lake and Park Dam is located approximately one-half mile upstream from the Memphis Reservoir.

Elevations within the watershed range from approximately 700 feet above MSL at the damsite to over 815 feet above MSL in the upper portion of the watershed.

A drainage map showing the watershed area is included in Appendix B.

Evaluation of the hydraulic and hydrologic features of Memphis Reservoir Dam was based on criteria set forth the the Corps of Engineers' Recommended Guidelines for Safety Inspection of Dams, and additional guidance provided by the St. Louis District of the Corps of Engineers. The Probable Maximum Flood (PMF) was calculated from the Probable Maximum Precipitation (PMP) using the methods outlined in the



U.S. Weather Bureau Publication, Hydrometeoroglogical Report No. 33. The probable maximum storm duration was set at 24 hours, and storm rainfall distribution was based on criteria given in EM 1110-2-1411 (Standard Project Storm). The SCS triangular hydrograph, transformed to a curvilinear hydrograph, was adopted for developing the unit hydrograph for drainage area between the upstream dam and the Memphis Reservoir. The derived unit hydrograph is presented in Appendix B.

Initial and infiltration loss rates were applied to the PMP to obtain rainfall excesses. The rainfall excesses were then applied to the unit hydrograph to obtain the PMF hydrograph, utilizing the Corps of Engineers' computer program HEC-1, (Dam Safety Version), which was prepared specifically for dam safety analysis. The computed peak discharge of the PMF and one-half of the PMF for drainage area between the upstream dam and Memphis Reservoir are 10,971 cfs and 5,486 cfs, respectively.

Both the PMF and one-half of the PMF inflow hydrographs for drainage area between the upstream dam and the Memphis Reservoir were added to the routed PMF, and one-half of the PMF from the upstream reservoir. The combined hydrographs were routed through the Memphis Reservoir by the Modified Puls Method, also utilizing the HEC-1 (Dam Safety Version) computer program. The peak outflow discharges for the PMF and one-half of the PMF at the Memphis Reservoir Dam are 15,358 cfs and 4,515 cfs, respectively. Both the PMF and one-half of the PMF, when routed through the reservoir, resulted in overtopping of the dam.

The stage-outflow relation for the spillways were prepared from field notes and sketches. The reservoir stage-capacity data were based on the U.S.G.S. quadrangle topographic maps in combination with data given in the National Dam Safety Inventory Table. Reservoir storage capacity included surcharge levels exceeding the top of the dam, and the spillway overtop rating curve assumed that the dam remains intact during routing. In the routing computations, the discharge through the outlet facilities was excluded due to its insignificant magnitude as compared to the total spillway discharge and the PMF. The spillway rating curves and the reservoir capacity curve are also presented in Appendix B.

b. Experience Data

No records of reservoir stage or spillway discharge are maintained for this site. However, according to interviews with local residents, the maximum reservoir level was never higher than the crest of the embankment.

c. Visual Observations

The service spillway structure is deteriorating. Vertical cracks, moderate erosion and spalling on the concrete were apparent. The right bank of the exit channel shows signs of a moderate degree of erosion and sloughing. There is grass growing in front of the spillway entrance of both the service spillway and the No. 2 spillway.

The emergency spillway is in adequate condition.

All the spillways and the exit channels are located at the furthestmost right abutment and are away from the downstream toe of the dam. Releases from the spillways will not endanger the integrity of the dam.

d. Overtopping Potential

As indicated in Section 5.1-a., both the Probable Maximum Flood and one-half of the Probable Maximum Flood, when routed through the reservoir, resulted in overtopping of the dam. The PMF and one-half of the PMF overtopped the dam crest by 3.93 feet and 1.23 feet, respectively. The total duration of embankment overflow is 9.0 hours during the PMF, and 3.83 hours during one-half of the PMF. The spillway of the Memphis Reservoir Dam is capable of passing a flood equal to approximately 25 percent of the PMF just before overtopping the dam. The 25 percent PMF has a frequency occurrence of less than the 1 percent chance flood. Since the PMF is the minimum Spillway Design Flood (SDF) for Memphis Reservoir Dam, according to the Recommended Guidelines for Safety Inspection of Dams by the Corps, the spillway capacity of the dam is considered "Inadequate".

The effect from rupture of the dam could extend approximately 2 miles downstream of the dam. There are two to three farmhouses, the Scotland County Fairgrounds, several farm buildings and one State Highway crossing within this 2 miles of floodplain area. The floodplain is extensively farmed.

## SECTION 6: STRUCTURAL STABILITY

### 6.1 Evaluation of Structural Stability

#### a. Visual Observations

There were no signs of settlement or distress observed on the embankment or foundation during the visual inspection. The upstream slope, crest, and downstream slope are well protected by either riprap or vegetation. Seepage was not observed on the downstream slope or beyond the toe of the embankment. The small trees and brush beginning to grow on the upstream embankment slope should be cleared.

The concrete spillway structures, although old and deteriorating, are in *satisfactory structural condition*. Some grouting to stop the leakage should be performed, and patching of badly spalled areas should be done as it becomes necessary.

The downstream channel may require remedial work following discharges through the spillway during flood conditions, but no immediate remedial work is required at this time.

No problems were observed with the water supply outlet which would jeopardize the safety of the dam.

b. Design and Construction Data

No design or construction data relating to the structural stability of the dam or appurtenant structures were found.

c. Operating Records

No operating records are available relating to the stability of the dam or appurtenant structures. Water levels have not been recorded, however, the dam was within 1 inch of being full on the day of inspection, and is assumed to be close to full at all times. The only operation facility at the dam is the water supply outlet pipe.

d. Post Construction Changes

No post construction changes exist which will affect the structural stability of the dam. At spillway No. 2, the new spillway wall replaced an old wall which had failed.

e. Seismic Stability

In general, projects located in Seismic Zones 0, 1 and 2 can be assumed to present no hazard from earthquake, provided the static stability conditions are satisfactory and conventional safety margins exist. Memphis Reservoir Dam is located in Seismic Zone 1. A detailed seismic analysis is not felt to be necessary for this embankment.

## SECTION 7: ASSESSMENT/REMEDIAL MEASURES

### 7.1 Dam Assessment

The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

It should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team.

It is also important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that an unsafe condition could be detected.

#### a. Safety

The spillway capacity at Memphis Reservoir Dam was found to be inadequate. The spillway is capable of passing a flood equal to 25 percent of the PMF.

The general physical condition of the dam and appurtenant structures is fair. The leakage through the service spillway crest should be stopped, and patchwork to the deteriorating concrete should be done as it becomes necessary.

The vegetation should be cleared from the approach channels to the spillway.

The trees starting to grow on the upstream embankment slope should be cut before they become a hazard to the embankment. The downstream embankment slope should be maintained in its present condition.

b. Adequacy of Information

Information concerning operation and maintenance of the dam and appurtenant structures is somewhat lacking. It is recommended that the following programs be initiated to help alleviate this problem:

1. Periodic inspection of the dam by an engineer experienced in design and construction of earth dams.
2. Set up a maintenance schedule and log all visits to the dam for operation, repairs and maintenance.
3. The dam should be surveyed and an as-built set of plans and drawings should be completed.
4. Perform seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams".

c. Urgency

The remedial measures recommended in Paragraph 7.2 should be accomplished in the near future.

Increasing the spillway capacity is of a more urgent nature than the other recommended actions.

d. Necessity for Phase II Inspection

Based on results of the Phase I inspection, and if the remedial measures recommended in Paragraph 7.2 are undertaken as soon as possible, a Phase II inspection is not felt to be necessary.

7.2 Remedial Measures

a. The spillway size and/or height of the dam should be increased to pass the Probable Maximum Flood.


b. O & M Maintenance Procedures

1. Periodic inspection of the dam by an engineer experienced in design and construction of earth dams.
2. Set up a maintenance schedule and log all visits to the dam for operation, repairs and maintenance.





3. The dam should be surveyed and an as-built set of plans and drawings should be completed.
4. Cut the small trees and brush on the upstream embankment slope.
5. Clear the vegetation from the approach channels of the spillways.
6. Patch the eroded and spalled concrete on the spillway structure as it becomes necessary.
7. Seepage and stability analyses should be performed by a professional engineer experienced in the design and construction of dams.

PLATES




LOCATION MAP  
MEMPHIS RESERVOIR DAM  
SCOTLAND COUNTY, MISSOURI





**TYPICAL SECTION**


**MEMPHIS RESERVOIR DAM  
PLAN AND SECTION**



# MEMPHIS LAKE DAM











NO. 100	DATE	1942
JAMES EARL RAY, JR.		
MEMPHIS, TENNESSEE		
1942 MAY 17 11 AM '42		





Runway  
Canal  
Ditch

Runway  
Canal  
Ditch

DATE	10/10/50
BY	W. J. ...
FOR	...
APPROVED	...
DATE	10/10/50
BY	...
FOR	...
APPROVED	...







### Explanation

#### Pennsylvanian System

- P<sub>kc</sub> - Kansas City group: cyclic deposits with numerous limestones.
- P<sub>pwm</sub> - Pleasanton group: sandstone channel member.
- P<sub>m</sub> - Marmaton group: cyclic deposits with limestones.
- P<sub>cc</sub> - Cherokee group: cyclic deposits, predominately shale, sandstone and coal beds.

#### Mississippian System

- M<sub>m</sub> - sandy, oolitic, fossiliferous, lithographic, or cherty limestones.
- M<sub>o</sub> - cherty, crinoidal limestone, with some shale.
- M<sub>k</sub> - intercalated limestones and shales.

Reference: Geologic Map of Missouri, 1961, Division of Geological Survey and Water Resources, State of Missouri.

General Geologic Map

APPENDIX A

PHOTOGRAPHS TAKEN DURING INSPECTION

### MEMPHIS RESERVOIR DAM

- Photo 1 - View along crest of dam taken from near left abutment.
- Photo 2 - Picture of upstream slope of embankment taken from left side of dam.
- Photo 3 - Picture of crest and downstream embankment slope taken from near center of dam looking toward left abutment.
- Photo 4 - Picture of downstream embankment slope taken from near center of dam looking toward left abutment.
- Photo 5 - Picture of intake structure for water supply piping.
- Photo 6 - Picture of pump house vault for water supply.
- Photo 7 - Picture of downstream channel of spillway taken from near center of dam toward right side of dam.
- Photo 8 - Picture of concrete overflow crest of service spillway taken at left side of spillway.
- Photo 9 - Picture of concrete overflow of service spillway taken from downstream of spillway.
- Photo 10 - Picture of downstream discharge channel with energy dissipators below service spillway.
- Photo 11 - Picture of emergency spillway approach channel and crest.
- Photo 12 - Picture of crest of emergency spillway and failed downstream wall taken from right abutment of spillway.
- Photo 13 - Picture of drop downstream of emergency spillway.

Memphis Reservoir Dam



Photo 1 - View along crest of dam taken from near left abutment.



Photo 2 - Picture of upstream slope of embankment taken from left side of dam.



Photo 3 - Picture of crest and downstream embankment slope taken from near center of dam looking toward left abutment.



Photo 4 - Picture of downstream embankment slope taken from near center of dam looking toward left abutment.



Memphis Reservoir Dam




Photo 5 - Picture of intake structure for water supply piping.




Photo 6 - Picture of pump house vault for water supply.



Photo 7 - Picture of downstream channel of spillway taken from near center of dam toward right side of dam.




Photo 8 - Picture of concrete overflow crest of service spillway taken at left side of spillway.




Photo 9 - Picture of concrete overflow of service spillway taken from downstream of spillway.




Photo 10 - Picture of downstream discharge channel with energy dissipators below service spillway.

Memphis Reservoir Dam



Photo 11 - Picture of emergency spillway approach channel and crest.



Photo 12 - Picture of crest of emergency spillway and failed downstream wall taken from right abutment of spillway.





Photo 13 - Picture of emergency spillway downstream of concrete weir.

APPENDIX B  
HYDROLOGIC COMPUTATIONS



MEMPHIS RESERVOIR DAM  
DRAINAGE AREA

## MISSOURI DAM SAFETY INSPECTION

MEMPHIS RESERVOIR DAM (OLD.)

RESERVOIR AREA CAPACITY DATA

SHEET NO. 1 OF

JOB NO. 1223-001-1


BY HLB DATE 4-10-78

MEMPHIS RESERVOIR DAM (OLD)RESERVOIR AREA CAPACITY DATA.

ELEV. FT.	RESERVOIR SURFACE AREA (ACRES)	INCREMENTAL VOLUME (AC-FT)	TOTAL VOLUME (AC-FT)	REMARKS
701	0.6	—	0	ASSUMED STREAM BED AT CENTER OF DAM
706	4.8	9.0	9.0	DATA FROM CONSTRUCTION PLANS
711	21.2	64.9	73.9	DATA FROM CONSTRUCTION PLANS
716	40.0	152.9	226.8	DATA FROM CONSTRUCTION PLANS
716.2	40.6 *	8	235.0 *	SPILLWAY CREST EL.
720	51.9	173.5	410.5	DATA FROM CONSTRUCTION PLANS
720.2	53.8 *	10.6	421.0 *	TOP OF DAM.
730	145.4	976.0	1397.0	AREA FROM U.S.G.S. MAP
740	259.1	2022.5	3419.5	AREA FROM U.S.G.S. MAP.

\* INTERPOLATED DATA.





MEMPHIS RESERVOIR DAM  
RESERVOIR CAPACITY CURVE

DAM SAFETY INSPECTION / MISSOURI

MEMPHIS RESERVOIR DAM


FILLWAY & OVERTOP DISCHARGE CAPACITY

SHEET NO. 1 OF


JOB NO. 1223-001

BY MAS  
KLB

DATE 11/12/78



ELEV. FT.	$H_1$	$H_2$	$H_3$	$H_4$	$H_5$	$L_1$	$L_2$	$L_3$	$L_4$	$L_5$	$C_1$	$C_2$	$C_3$	$C_4$	$C_5$	$\sum_{i=1}^5 C_i L_i H_i$
716.2	0.0					58										0.0
716.7	0.5					58	57.19				2.63					54
717.1	0.9					58	57.17				2.66					132
717.4	1.2	0.3				58	57.19				2.64	2.71				226
717.7	1.5	0.6	0.0			58	57.19	75			2.66	2.75				356
718.2	2.0	1.1	0.5			58	57.17	75			2.72	3.03				718
718.7	2.5	1.6	1.0	0.0		58	57.17	75	85.81		2.81	3.28	2.63			1221
719.5	3.3	2.4	1.8	0.8		58	57.19	75	85.81		2.95	3.31	2.63			2381
720.2	4.0	3.1	2.5	1.5	0.0	58	57.17	75	85.81	854	3.07	3.32	2.63	2.85		3751
721.0	4.8	3.7	3.3	2.3	0.8	58	57.19	75	85.81	854	3.32	3.32	2.63	3.31	2.69	7273
723.0	6.8	5.9	5.3	4.3	2.8	58	57.19	75	85.81	854	3.32	3.32	2.63	3.32	2.63	21606
725.0	8.8	7.7	7.3	6.3	4.8	58	57.19	75	85.81	854	3.32	3.32	2.63	3.32	2.63	41258
727.0	10.8	9.9	7.3	6.3	6.8	58	57.17	75	85.81	854	3.32	3.32	2.63	3.32	2.63	64981
730.0	13.8	12.2	12.3	11.3	9.8	58	57.17	75	85.81	854	3.32	3.32	2.63	3.32	2.63	103525



MEMPHIS RESERVOIR DAM  
SPILLWAY & OVERTOP RATING  
CURVE

DAM SAFETY INSPECTION - MISSOURI  
MEMPHIS RESERVOIR DAM  
UNIT HYDROGRAPH PARAMETERS

SHEET NO. 1 OF  
JOB NO. 1223-001-1  
BY KLG DATE 11-7-78

1. DRAINAGE AREA,  $A = 947 \text{ AC} = \underline{1.48 \text{ SQ. MI}}$

2. LENGTH OF STREAM,  $L = 1.44 \text{ MI}$

3. DIFFERENCE IN ELEV.,  $\Delta H = 815 - 719 = 96 \text{ FT.}$

4. TIME OF CONCENTRATION,  $T_c$

$$T_c = \left( \frac{11.9 \times L^3}{\Delta H} \right)^{0.385}$$

$$T_c = \left( \frac{11.9 \times 1.44^3}{96} \right)^{0.385}$$

$$T_c = \underline{0.68}$$

5. LAG TIME,  $L_t = 0.6 \times T_c$

$$L_t = 0.6 \times 0.68 = 0.41$$

6. RAINFALL UNIT DURATION,  $D$

$$D = \frac{L_t}{4} = \frac{0.41}{4} = 0.10$$

$$\text{USE } D = 5 \text{ min} = 0.083 \text{ HR}$$

TO MATCH UPSTREAM CALCULATIONS

7. TIME TO PEAK,  $T_p$

$$T_p = \frac{D}{2} + 0.6 \times T_c$$

$$T_p = \frac{0.083}{2} + 0.6 \times 0.68$$

$$T_p = \underline{0.45 \text{ HR.}}$$


8.  $q_p = \frac{484 \times A}{T_p} = \frac{484 \times 1.48}{0.45} = \underline{1592 \text{ CFS.}}$

DAM SAFETY INSPECTION - MISSOURI  
MEMPHIS RESERVOIR  
UNIT HYDROGRAPH DERIVATION

SHEET NO. 2 OF  
JOB NO. 1223-001-1  
BY KLB DATE 11-7-78

7) CURVILINEAR UNIT HYDROGRAPH

TIME, $T/T_p$	DISCHARGE RATIO $q/q_p$	UNIT HYDROGRAPH	
		TIME, T (HRS)	DISCHARGE $q$ (CFS)
0.000	0.000	0.000	0.000
0.1	0.015	0.05	23.88
0.2	0.075	0.09	119.40
0.3	0.16	0.14	254.72
0.4	0.28	0.18	445.76
0.5	0.45	0.23	716.40
0.6	0.60	0.27	955.20
0.7	0.77	0.32	1225.84
0.8	0.89	0.36	1416.88
0.9	0.97	0.41	1549.24
1.0	1.00	0.45	1592.00
1.1	0.98	0.50	1560.16
1.2	0.92	0.54	1464.64
1.3	0.84	0.59	1337.28
1.4	0.75	0.63	1194.00
1.5	0.66	0.68	1050.72
1.6	0.56	0.72	891.52
1.8	0.42	0.81	668.64
2.0	0.32	0.90	509.44
2.2	0.24	0.99	382.08
2.4	0.18	1.08	286.56
2.6	0.13	1.17	206.96
2.8	0.098	1.26	156.02
3.0	0.075	1.35	119.40
3.5	0.036	1.58	57.31
4.0	0.018	1.80	28.66
4.5	0.009	2.03	14.33
5.0	0.004	2.25	6.37



MEMPHIS RESERVOIR DAM  
5 MINUTE UNIT HYDROGRAPH

DAM SALW INDIAN/MISSOURI

SHEET NO. 1 OF

MEMPHIS RESERVOIR DAM

JOB NO. 1223-001

- PROBABLE MAXIMUM STORM (PMS)

BY MAS DATE

DETERMINATION OF PMS

1. Determine drainage area of the basin

$$D.A. = 947 \text{ acres} = 1.48 \text{ Sq. mi.}$$

2. Determine PMP Index rainfall:

Location of centroid of basin:

$$\text{Long. } 92.21^{\circ}; \text{ Lat. } 40.44^{\circ}$$

$$\rightarrow \text{PMP for } 200 \text{ Sq. mi. \& 24 hrs duration} \\ = 23.8" (\text{from Fig 1, HMR NO 33})$$


3. Determine basin rainfall in terms of percentage of PMP Index rainfall for various durations:

$$\text{Location: Long. } 92.21^{\circ}; \text{ Lat. } 40.44^{\circ}$$

$$\Rightarrow \text{Zone 7}$$

Duration (Hrs.)	Percent of Index rainfall (%)	Total rainfall (Inches)	Rainfall increments (Inches)	Duration of incre- ment (Hrs.)
6	100	23.8	23.8	6
12	120	28.6	4.8	6
24	130	30.9	2.3	12

93 91 89



23.8"

MEMPHIS RESERVOIR DAM  
DETERMINATION OF PMP



DAM SAFETY INSPECTION - MISSOURI

SHEET NO. 1 OF 1

MEMPHIS RESERVOIR (OLD)

JOB NO. 1223-001-1

100 YEAR FLOOD BY REGRESSION EQUATION BY KLR DATE 11-20-78

MEMPHIS RESERVOIR

100 YEAR FLOOD BY REGRESSION EQUATION

REGRESSION EQUATION FOR 100 YEAR FLOOD FOR

MISSOURI:

$$Q_{100} = 85.1 A^{0.934} A^{-0.02} S^{0.576}$$

WHERE:

A = DRAINAGE AREA IN SQ. MI.

S = MAIN CHANNEL SLOPE FE/MI.

(AVG. SLOPE BETWEEN 0.1 L AND 0.95 L

L, BEING LENGTH OF MAIN CHANNEL)

FOR MEMPHIS RESERVOIR:

$$A = 1.48 \text{ SQ. MI.}$$

$$S = \frac{795 - 727}{0.75 \times 1.44} = 62.96 \text{ FE/MI.}$$

$$Q_{100} = 85.1 (1.48)^{0.934} (1.48)^{-0.02} (62.96)^{0.576}$$

$$= \underline{\underline{1330 \text{ CFS}}}$$

HEC1DB INPUT DATA



31	9.0	73.0	226.0	233.0	410.3	421.0	1397.0	3419.5
32	701	700	710	540.2	780.0	780.2	730	740
33	710.8							
34	720.2							
35	730.6							

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT	13
ROUTE HYDROGRAPH TO	3
RUNOFF HYDROGRAPH AT	16
COMBINE 2 HYDROGRAPHS AT	16
ROUTE HYDROGRAPH TO	16
END OF NETWORK	

INFLOW PMF AND ONE-HALF PMF HYDROGRAPH COMPUTATION  
FOR NEW MEMPHIS RESERVOIR

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (REV-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 31 AUG 78  
 \*\*\*\*\*

RUN DATE= 78/11/29  
 TIME= 12.19.50.

DAM SAFETY INSPECTION - MISSOURI  
 KENNETHS RESERVOIR (NEW AND OLD)  
 PMP AND 50 PERCENT PMP DETERMINATION AND ROUTING

JOB SPECIFICATION  
 NO NHR NMN TOAY IHR IMIN METRC IPLT IPRT NSTAN  
 300 0 5 0 0 0 0 0 0 0  
 JOPEX 5 0 0 0 0 0 0 0 0 0

MULTI-PLAN ANALYSES TO BE PERFORMED  
 MPLANS 1 NRATIO= 2 LRTIME 1

RTIME= 1.00 .59

\*\*\*\*\* SUB-AREA RUNOFF COMPUTATION \*\*\*\*\*

INPUT PMP INDEX PRECIPITATION AND RATIOS, INPUT RES UNIT  
 IRTAB ICOMP IECOM IYAPE JPLT JPT INAME ISTATE IAUO  
 3 0 0 0 0 0 1 0 0

HYDROGRAPH DATA  
 INYDO IUNG TAREA SNAP T880A TR8PC RATIO ISHOW ISAME LOCAL  
 1 -1 3.05 0.00 3.95 1.00 0.00 0 0 0

PRECIP DATA  
 APPE PHS R6 R12 R24 R48 R72 R96  
 0.00 23.00 100.00 120.00 150.00 0.00 0.00 0.00

LOSS DATA  
 LROBY STARR OLTR RTOL ERAIN STARR RTIOK STRIL CNSTL ALBHR RTIMP  
 0 0.00 0.00 1.00 0.00 0.00 1.00 .85 .07 0.00 0.00

GIVEN UNIT GRAPH, MUHGR= 22  
 0. 480. 1800. 3800. 5100. 2900. 2100. 1450. 1020.  
 100. 500. 800. 170. 100. 100. 50. 30.

UNIT GRAPH TOTALS 23032. CFS OR 1.01 INCHES OVER THE AREA

RECESSION DATA  
 RTIME= 1.00

MO,DA NR,MN PERIOD DAIN ERSS LOSS COMF 0 MO,DA NR,MN PERIOD RAIN ERSS LOSS COMF 8





1.01	5.05	61	0.01	0.00	0.01	0.	1.01	17.35	211	.22	2.01	0.01	9091
1.01	5.05	62	0.01	0.00	0.01	0.	1.01	17.40	812	.22	2.01	0.01	9092
1.01	5.05	63	0.01	0.00	0.01	0.	1.01	17.45	213	.22	2.01	0.01	9093
1.01	5.05	64	0.01	0.00	0.01	0.	1.01	17.50	214	.22	2.01	0.01	9094
1.01	5.05	65	0.01	0.01	0.01	0.	1.01	17.55	215	.22	2.01	0.01	9095
1.01	5.05	66	0.01	0.01	0.01	0.	1.01	18.00	216	.22	2.01	0.01	9096
1.01	5.05	67	0.01	0.01	0.01	0.	1.01	18.05	217	.22	2.01	0.01	9097
1.01	5.05	68	0.01	0.01	0.01	0.	1.01	18.10	218	.22	2.01	0.01	9098
1.01	5.05	69	0.01	0.01	0.01	0.	1.01	18.15	219	.22	2.01	0.01	9099
1.01	5.05	70	0.01	0.01	0.01	0.	1.01	18.20	220	.22	2.01	0.01	9100
1.01	5.05	71	0.01	0.01	0.01	0.	1.01	18.25	221	.22	2.01	0.01	9101
1.01	5.05	72	0.01	0.01	0.01	0.	1.01	18.30	222	.22	2.01	0.01	9102
1.01	5.05	73	0.01	0.01	0.01	0.	1.01	18.35	223	.22	2.01	0.01	9103
1.01	5.05	74	0.01	0.01	0.01	0.	1.01	18.40	224	.22	2.01	0.01	9104
1.01	5.05	75	0.01	0.01	0.01	0.	1.01	18.45	225	.22	2.01	0.01	9105
1.01	5.05	76	0.01	0.01	0.01	0.	1.01	18.50	226	.22	2.01	0.01	9106
1.01	5.05	77	0.01	0.01	0.01	0.	1.01	18.55	227	.22	2.01	0.01	9107
1.01	5.05	78	0.01	0.01	0.01	0.	1.01	19.00	228	.22	2.01	0.01	9108
1.01	5.05	79	0.01	0.01	0.01	0.	1.01	19.05	229	.22	2.01	0.01	9109
1.01	5.05	80	0.01	0.01	0.01	0.	1.01	19.10	230	.22	2.01	0.01	9110
1.01	5.05	81	0.01	0.01	0.01	0.	1.01	19.15	231	.22	2.01	0.01	9111
1.01	5.05	82	0.01	0.01	0.01	0.	1.01	19.20	232	.22	2.01	0.01	9112
1.01	5.05	83	0.01	0.01	0.01	0.	1.01	19.25	233	.22	2.01	0.01	9113
1.01	5.05	84	0.01	0.01	0.01	0.	1.01	19.30	234	.22	2.01	0.01	9114
1.01	5.05	85	0.01	0.01	0.01	0.	1.01	19.35	235	.22	2.01	0.01	9115
1.01	5.05	86	0.01	0.01	0.01	0.	1.01	19.40	236	.22	2.01	0.01	9116
1.01	5.05	87	0.01	0.01	0.01	0.	1.01	19.45	237	.22	2.01	0.01	9117
1.01	5.05	88	0.01	0.01	0.01	0.	1.01	19.50	238	.22	2.01	0.01	9118
1.01	5.05	89	0.01	0.01	0.01	0.	1.01	19.55	239	.22	2.01	0.01	9119
1.01	5.05	90	0.01	0.01	0.01	0.	1.01	20.00	240	.22	2.01	0.01	9120
1.01	5.05	91	0.01	0.01	0.01	0.	1.01	20.05	241	.22	2.01	0.01	9121
1.01	5.05	92	0.01	0.01	0.01	0.	1.01	20.10	242	.22	2.01	0.01	9122
1.01	5.05	93	0.01	0.01	0.01	0.	1.01	20.15	243	.22	2.01	0.01	9123
1.01	5.05	94	0.01	0.01	0.01	0.	1.01	20.20	244	.22	2.01	0.01	9124
1.01	5.05	95	0.01	0.01	0.01	0.	1.01	20.25	245	.22	2.01	0.01	9125
1.01	5.05	96	0.01	0.01	0.01	0.	1.01	20.30	246	.22	2.01	0.01	9126
1.01	5.05	97	0.01	0.01	0.01	0.	1.01	20.35	247	.22	2.01	0.01	9127
1.01	5.05	98	0.01	0.01	0.01	0.	1.01	20.40	248	.22	2.01	0.01	9128
1.01	5.05	99	0.01	0.01	0.01	0.	1.01	20.45	249	.22	2.01	0.01	9129
1.01	5.05	100	0.01	0.01	0.01	0.	1.01	20.50	250	.22	2.01	0.01	9130
1.01	5.05	101	0.01	0.01	0.01	0.	1.01	20.55	251	.22	2.01	0.01	9131
1.01	5.05	102	0.01	0.01	0.01	0.	1.01	21.00	252	.22	2.01	0.01	9132
1.01	5.05	103	0.01	0.01	0.01	0.	1.01	21.05	253	.22	2.01	0.01	9133
1.01	5.05	104	0.01	0.01	0.01	0.	1.01	21.10	254	.22	2.01	0.01	9134
1.01	5.05	105	0.01	0.01	0.01	0.	1.01	21.15	255	.22	2.01	0.01	9135
1.01	5.05	106	0.01	0.01	0.01	0.	1.01	21.20	256	.22	2.01	0.01	9136
1.01	5.05	107	0.01	0.01	0.01	0.	1.01	21.25	257	.22	2.01	0.01	9137
1.01	5.05	108	0.01	0.01	0.01	0.	1.01	21.30	258	.22	2.01	0.01	9138
1.01	5.05	109	0.01	0.01	0.01	0.	1.01	21.35	259	.22	2.01	0.01	9139
1.01	5.05	110	0.01	0.01	0.01	0.	1.01	21.40	260	.22	2.01	0.01	9140
1.01	5.05	111	0.01	0.01	0.01	0.	1.01	21.45	261	.22	2.01	0.01	9141
1.01	5.05	112	0.01	0.01	0.01	0.	1.01	21.50	262	.22	2.01	0.01	9142
1.01	5.05	113	0.01	0.01	0.01	0.	1.01	21.55	263	.22	2.01	0.01	9143
1.01	5.05	114	0.01	0.01	0.01	0.	1.01	22.00	264	.22	2.01	0.01	9144
1.01	5.05	115	0.01	0.01	0.01	0.	1.01	22.05	265	.22	2.01	0.01	9145
1.01	5.05	116	0.01	0.01	0.01	0.	1.01	22.10	266	.22	2.01	0.01	9146
1.01	5.05	117	0.01	0.01	0.01	0.	1.01	22.15	267	.22	2.01	0.01	9147
1.01	5.05	118	0.01	0.01	0.01	0.	1.01	22.20	268	.22	2.01	0.01	9148
1.01	5.05	119	0.01	0.01	0.01	0.	1.01	22.25	269	.22	2.01	0.01	9149
1.01	5.05	120	0.01	0.01	0.01	0.	1.01	22.30	270	.22	2.01	0.01	9150





PMF HYDROGRAPH ROUTING

NEW MEMPHIS RESERVOIR

[illegible]

ROUTE	HYDROGRAPH	THROUGH	NEW	MEMPHIS	RESERVOIR	JPRPT	INAME	ISTAGE	IAUT0
1STAN	ICDHP	1	0	0	0	0	1	0	0

BLOSS	CLOS	AVG	IRF	ISAME	INPT	IPMP	LSTR
0.0	0.000	0.00	1	1	0	0	0

	MS399	MS30L	LAC	AMSKX	X	ISK	STORA	ISPRAT	
	0	0	0	0.000	0.000	0.000	-770.	-1	
STORAGE	111.0	112.0	113.0	114.0	115.5	117.0	119.0	121.3	122.7
	116.0								
	124.1								

	0.	86.	207,	485,	1317,	2918,	7565,	14036,	28029,
FLOW	46787,								

DATE	AMOUNT	REMARKS
0. 20.	301.	
0. 20.	409.	
0. 20.	5164.	
0. 20.	7030.	
0. 20.	7065.	

ELEVATIONS	725.	730.	740.	750.	760.	770.	774.	780.	790.
------------	------	------	------	------	------	------	------	------	------

CNEL	SPWID	COOM	EPM	ELEV	COGL	CAREA	EXPL
770.0	0.0	0.0	0.0	0.0	0.0	0.0	D.D

DAM DATA	
CQDQ	EXPD DAMID
0.0	0.0
709.0	0.0

STATION 3, PLAN 1, RATIO 1

END-OF-PERIOD HYDROGRAPH ORDINATES

**outflow**

[illegible]



ONE-HALF PMF HYDROGRAPH

NEW MEMPHIS RESERVOIR

770.9	770.9	770.9	771.0	771.1	771.1	771.1	771.1	771.2	771.5
771.2	771.3	771.3	771.3	771.4	771.4	771.4	771.5	771.5	771.5
771.6	771.7	771.7	771.7	771.7	771.8	771.8	771.9	771.9	771.9
771.9	771.9	771.9	772.0	772.0	772.0	772.1	772.1	772.1	772.3
772.2	772.3	772.3	772.3	772.3	772.3	772.4	772.4	772.5	772.5
772.6	772.7	772.8	772.9	773.0	773.1	773.2	773.3	773.4	773.6
773.7	773.8	773.9	774.0	774.1	774.3	774.4	774.5	774.7	774.7
774.8	775.0	775.0	775.1	775.2	775.4	775.5	775.7	775.8	775.8
775.9	776.1	776.2	776.3	776.4	776.5	776.6	776.7	776.8	777.0
777.9	778.4	778.6	779.1	779.3	779.4	779.7	779.7	779.7	779.8
779.6	779.6	779.6	779.6	779.8	779.7	779.7	779.7	779.7	779.7
779.6	779.6	779.5	779.5	779.5	779.4	779.4	779.4	779.3	779.3
779.2	779.1	779.0	778.9	778.8	778.7	778.6	778.5	778.4	778.3
778.2	778.1	778.0	777.9	777.8	777.7	777.6	777.5	777.4	777.4
777.3	777.3	777.2	777.1	777.1	777.0	777.0	776.9	776.8	776.8
776.7	776.7	776.6	776.5	776.5	776.5	776.4	776.4	776.3	776.3
776.3	776.2	776.2	776.1	776.1	776.1	776.0	776.0	776.0	776.0
775.9	775.9	775.9	775.8	775.8	775.8	775.7	775.7	775.7	775.7
775.6	775.6	775.6	775.6	775.6	775.5	775.5	775.5	775.4	775.4
775.4	775.4	775.4	775.3	775.3	775.3	775.3	775.2	775.2	775.2

STATION 3, PLAN 1, RATIO 2  
END-OF-PERIOD HYDROGRAPH ORDINATES[illegible]





INFLOW PMF AND ONE-HALF PMF

OLD MEMPHIS RESERVOIR

(Local Flows)

772.5	772.6	772.7	772.8	772.9	773.0	773.1	773.2
773.3	773.4	773.5	773.6	773.7	773.8	773.9	774.0
774.1	774.2	774.3	774.4	774.5	774.6	774.7	774.8
774.9	775.0	775.1	775.2	775.3	775.4	775.5	775.6
775.7	775.8	775.9	776.0	776.1	776.2	776.3	776.4
776.5	776.6	776.7	776.8	776.9	777.0	777.1	777.2
777.3	777.4	777.5	777.6	777.7	777.8	777.9	778.0
778.1	778.2	778.3	778.4	778.5	778.6	778.7	778.8
778.9	779.0	779.1	779.2	779.3	779.4	779.5	779.6
779.7	779.8	779.9	780.0	780.1	780.2	780.3	780.4
780.5	780.6	780.7	780.8	780.9	781.0	781.1	781.2
781.3	781.4	781.5	781.6	781.7	781.8	781.9	782.0
782.1	782.2	782.3	782.4	782.5	782.6	782.7	782.8
782.9	783.0	783.1	783.2	783.3	783.4	783.5	783.6
783.7	783.8	783.9	784.0	784.1	784.2	784.3	784.4
784.5	784.6	784.7	784.8	784.9	785.0	785.1	785.2
785.3	785.4	785.5	785.6	785.7	785.8	785.9	786.0
786.1	786.2	786.3	786.4	786.5	786.6	786.7	786.8
786.9	787.0	787.1	787.2	787.3	787.4	787.5	787.6
787.7	787.8	787.9	788.0	788.1	788.2	788.3	788.4
788.5	788.6	788.7	788.8	788.9	789.0	789.1	789.2
789.3	789.4	789.5	789.6	789.7	789.8	789.9	790.0
790.1	790.2	790.3	790.4	790.5	790.6	790.7	790.8
790.9	791.0	791.1	791.2	791.3	791.4	791.5	791.6
791.7	791.8	791.9	792.0	792.1	792.2	792.3	792.4
792.5	792.6	792.7	792.8	792.9	793.0	793.1	793.2
793.3	793.4	793.5	793.6	793.7	793.8	793.9	794.0
794.1	794.2	794.3	794.4	794.5	794.6	794.7	794.8
794.9	795.0	795.1	795.2	795.3	795.4	795.5	795.6
795.7	795.8	795.9	796.0	796.1	796.2	796.3	796.4
796.5	796.6	796.7	796.8	796.9	797.0	797.1	797.2
797.3	797.4	797.5	797.6	797.7	797.8	797.9	798.0
798.1	798.2	798.3	798.4	798.5	798.6	798.7	798.8
798.9	799.0	799.1	799.2	799.3	799.4	799.5	799.6
799.7	799.8	799.9	800.0	800.1	800.2	800.3	800.4
800.5	800.6	800.7	800.8	800.9	801.0	801.1	801.2
801.3	801.4	801.5	801.6	801.7	801.8	801.9	802.0
802.1	802.2	802.3	802.4	802.5	802.6	802.7	802.8
802.9	803.0	803.1	803.2	803.3	803.4	803.5	803.6
803.7	803.8	803.9	804.0	804.1	804.2	804.3	804.4
804.5	804.6	804.7	804.8	804.9	805.0	805.1	805.2
805.3	805.4	805.5	805.6	805.7	805.8	805.9	806.0
806.1	806.2	806.3	806.4	806.5	806.6	806.7	806.8
806.9	807.0	807.1	807.2	807.3	807.4	807.5	807.6
807.7	807.8	807.9	808.0	808.1	808.2	808.3	808.4
808.5	808.6	808.7	808.8	808.9	809.0	809.1	809.2
809.3	809.4	809.5	809.6	809.7	809.8	809.9	810.0
810.1	810.2	810.3	810.4	810.5	810.6	810.7	810.8
810.9</							

INPUT PHA-	INDEX	PRECIPITATION	RATIOS.	INPUT.	SCS	UNIT					
I8TAQ	I8TAC	I8COMP	I8TECON	I8TYAPE	J8JLT	J8PRT	I8NAME	I8STAGE	I8AUTO	I8	I8
0	0	0	0	0	0	0	1	0	0	0	0

HYDROGRAPH DATA									
TIME	SNAP	TRDA	TRSPC	RATIO	ISNOM	ISAME	LOCAL		
0000	0.00	1.00	1.00	0.000	0	0	0		
0005	0.00	1.00	1.00	0.000	0	0	0		
0010	0.00	1.00	1.00	0.000	0	0	0		
0015	0.00	1.00	1.00	0.000	0	0	0		
0020	0.00	1.00	1.00	0.000	0	0	0		
0025	0.00	1.00	1.00	0.000	0	0	0		
0030	0.00	1.00	1.00	0.000	0	0	0		
0035	0.00	1.00	1.00	0.000	0	0	0		
0040	0.00	1.00	1.00	0.000	0	0	0		
0045	0.00	1.00	1.00	0.000	0	0	0		
0050	0.00	1.00	1.00	0.000	0	0	0		
0055	0.00	1.00	1.00	0.000	0	0	0		
0100	0.00	1.00	1.00	0.000	0	0	0		
0105	0.00	1.00	1.00	0.000	0	0	0		
0110	0.00	1.00	1.00	0.000	0	0	0		
0115	0.00	1.00	1.00	0.000	0	0	0		
0120	0.00	1.00	1.00	0.000	0	0	0		
0125	0.00	1.00	1.00	0.000	0	0	0		
0130	0.00	1.00	1.00	0.000	0	0	0		
0135	0.00	1.00	1.00	0.000	0	0	0		
0140	0.00	1.00	1.00	0.000	0	0	0		
0145	0.00	1.00	1.00	0.000	0	0	0		
0150	0.00	1.00	1.00	0.000	0	0	0		
0155	0.00	1.00	1.00	0.000	0	0	0		
0200	0.00	1.00	1.00	0.000	0	0	0		
0205	0.00	1.00	1.00	0.000	0	0	0		
0210	0.00	1.00	1.00	0.000	0	0	0		
0215	0.00	1.00	1.00	0.000	0	0	0		
0220	0.00	1.00	1.00	0.000	0	0	0		
0225	0.00	1.00	1.00	0.000	0	0	0		
0230	0.00	1.00	1.00	0.000	0	0	0		
0235	0.00	1.00	1.00	0.000	0	0	0		
0240	0.00	1.00	1.00	0.000	0	0	0		
0245	0.00	1.00	1.00	0.000	0	0	0		
0250	0.00	1.00	1.00	0.000	0	0	0		
0255	0.00	1.00	1.00	0.000	0	0	0		
0300	0.00	1.00	1.00	0.000	0	0	0		
0305	0.00	1.00	1.00	0.000	0	0	0		
0310	0.00	1.00	1.00	0.000	0	0	0		
0315	0.00	1.00	1.00	0.000	0	0	0		
0320	0.00	1.00	1.00	0.000	0	0	0		
0325	0.00	1.00	1.00	0.000	0	0	0		
0330	0.00	1.00	1.00	0.000	0	0	0		
0335	0.00	1.00	1.00	0.000	0	0	0		
0340	0.00	1.00	1.00	0.000	0	0	0		
0345	0.00	1.00	1.00	0.000	0	0	0		
0350	0.00	1.00	1.00	0.000	0	0	0		
0355	0.00	1.00	1.00	0.000	0	0	0		
0400	0.00	1.00	1.00	0.000	0	0	0		
0405	0.00	1.00	1.00	0.000	0	0	0		
0410	0.00	1.00	1.0						

	PRECIP DATA	R6	R12	R24	R48	R72	R96
SPFE	PM3						
A	21 00	100.00	120.00	110.00	0.00	0.00	0.00

LOSS DATA										
LEOPT	STRKR	OLYKR	WTIOL	ERAIN	STRKS	RTIOK	STATL	CNSTL	ALSHX	RTIMP
0.00	0.00	0.00	1.00	0.00	0.00	1.00	0.00	0.00	0.00	0.00

GIVEN UNIT GRAPH, NUMCOS 31			
0.	170.	870.	192.
10.	180.	1050.	1420.
20.	330.	200.	180.
30.	430.	200.	180.
40.	500.	170.	140.
50.	560.	110.	110.
60.	580.	80.	80.
70.	590.	50.	50.
80.	600.	30.	30.
90.	610.	10.	10.
100.	620.	0.	0.

UNIT GRAPH TOTALS 11565, CFS OR 1.01 INCHES OVER THE AREA

ACCESSION DATA	
STATUS	0.00
ORIGINS	0.00
AVIATION	1.00

END-OF-PERIOD FLOW

MO,DA	HR,MM	PERIOD	RAIN	EXCS	LOSS	COMP 0	MO,DA	HR,MM	PERIOD	RAIN	EXCS	LOSS	COMP 0
1.01	1.05	1	.01	0.00	.01	0	1.01	12.35	151	.80	.19	.01	1921.
1.01	1.10	2	.01	0.00	.01	0	1.01	12.40	152	.20	.19	.01	1916.
1.01	1.15	3	.01	0.00	.01	0	1.01	12.45	153	.20	.19	.01	1916.
1.01	1.20	4	.01	0.00	.01	0	1.01	12.50	154	.20	.19	.01	1924.
1.01	1.25	5	.01	0.00	.01	0	1.01	12.55	155	.20	.19	.01	1920.
1.01	1.30	6	.01	0.00	.01	0	1.01	13.00	156	.20	.19	.01	1994.
1.01	1.35	7	.01	0.00	.01	0	1.01	13.05	157	.24	.23	.01	2021.
1.01	1.40	8	.01	0.00	.01	0	1.01	13.10	158	.24	.23	.01	2099.
1.01	1.45	9	.01	0.00	.01	0	1.01	13.15	159	.24	.23	.01	2133.
1.01	1.50	10	.01	0.00	.01	0	1.01	13.20	160	.24	.23	.01	2177.
1.01	1.55	11	.01	0.00	.01	0	1.01	13.25	161	.24	.23	.01	2237.
1.01	1.00	12	.01	0.00	.01	0	1.01	13.30	162	.24	.23	.01	2308.
1.01	1.05	13	.01	0.00	.01	0	1.01	13.35	163	.24	.23	.01	2382.
1.01	1.10	14	.01	0.00	.01	0	1.01	13.40	164	.24	.23	.01	2444.
1.01	1.15	15	.01	0.00	.01	0	1.01	13.45	165	.24	.23	.01	2508.
1.01	1.20	16	.01	0.00	.01	0	1.01	13.50	166	.24	.23	.01	2551.
1.01	1.25	17	.01	0.00	.01	0	1.01	13.55	167	.24	.23	.01	2624.
1.01	1.30	18	.01	0.00	.01	0	1.01	14.00	168	.24	.23	.01	2688.
1.01	1.35	19	.01	0.00	.01	0	1.01	14.05	169	.30	.29	.01	2828.
1.01	1.40	20	.01	0.00	.01	0	1.01	14.10	170	.30	.29	.01	2845.
1.01	1.45	21	.01	0.00	.01	0	1.01	14.15	171	.30	.29	.01	2864.
1.01	1.50	22	.01	0.00	.01	0	1.01	14.20	172	.30	.29	.01	2701.
1.01	1.55	23	.01	0.00	.01	0	1.01	14.25	173	.30	.29	.01	2770.
1.01	2.00	24	.01	0.00	.01	0	1.01	14.30	174	.30	.29	.01	2859.
1.01	2.05	25	.01	0.00	.01	0	1.01	14.35	175	.30	.29	.01	2957.
1.01	2.10	26	.01	0.00	.01	0	1.01	14.40	176	.30	.29	.01	3046.
1.01	2.15	27	.01	0.00	.01	0	1.01	14.45	177	.30	.29	.01	3130.
1.01	2.20	28	.01	0.00	.01	0	1.01	14.50	178	.30	.29	.01	3188.
1.01	2.25	29	.01	0.00	.01	0	1.01	14.55	179	.30	.29	.01	3233.
1.01	2.30	30	.01	0.00	.01	0	1.01	15.00	180	.30	.29	.01	3267.
1.01	2.35	31	.01	0.00	.01	0	1.01	15.05	181	.18	.18	.01	3293.
1.01	2.40	32	.01	0.00	.01	0	1.01	15.10	182	.16	.16	.01	3314.
1.01	2.45	33	.01	0.00	.01	0	1.01	15.15	183	.16	.16	.01	3309.
1.01	2.50	34	.01	0.00	.01	0	1.01	15.20	184	.54	.54	.01	3297.
1.01	2.55	35	.01	0.00	.01	0	1.01	15.25	185	.63	.63	.01	3270.
1.01	3.00	36	.01	0.00	.01	0	1.01	15.30	186	1.54	1.53	.01	3334.
1.01	3.05	37	.01	0.00	.01	0	1.01	15.35	187	2.93	2.93	.01	3323.
1.01	3.10	38	.01	0.00	.01	0	1.01	15.40	188	.94	.94	.01	4042.
1.01	3.15	39	.01	0.00	.01	0	1.01	15.45	189	.63	.63	.01	5074.
1.01	3.20	40	.01	0.00	.01	0	1.01	15.50	190	.54	.54	.01	6783.
1.01	3.25	41	.01	0.00	.01	0	1.01	15.55	191	.36	.36	.01	8829.
1.01	3.30	42	.01	0.00	.01	0	1.01	16.00	192	.36	.36	.01	10327.
1.01	3.35	43	.01	0.00	.01	0	1.01	16.05	193	.28	.27	.01	10971.
1.01	3.40	44	.01	0.00	.01	0	1.01	16.10	194	.28	.27	.01	10747.
1.01	3.45	45	.01	0.00	.01	0	1.01	16.15	195	.28	.27	.01	10016.
1.01	3.50	46	.01	0.00	.01	0	1.01	16.20	196	.28	.27	.01	8695.
1.01	3.55	47	.01	0.00	.01	0	1.01	16.25	197	.28	.27	.01	7866.
1.01	4.00	48	.01	0.00	.01	0	1.01	16.30	198	.28	.27	.01	6615.
1.01	4.05	49	.01	0.00	.01	0	1.01	16.35	199	.28	.27	.01	5862.
1.01	4.10	50	.01	0.00	.01	0	1.01	16.40	200	.28	.27	.01	5224.
1.01	4.15	51	.01	0.00	.01	0	1.01	16.45	201	.28	.27	.01	4636.
1.01	4.20	52	.01	0.00	.01	0	1.01	16.50	202	.28	.27	.01	4111.
1.01	4.25	53	.01	0.00	.01	0	1.01	16.55	203	.28	.27	.01	3617.
1.01	4.30	54	.01	0.00	.01	0	1.01	17.00	204	.28	.27	.01	3223.
1.01	4.35	55	.01	0.00	.01	0	1.01	17.05	205	.22	.21	.01	3059.
1.01	4.40	56	.01	0.00	.01	0	1.01	17.10	206	.22	.21	.01	2922.
1.01	4.45	57	.01	0.00	.01	0	1.01	17.15	207	.22	.21	.01	2818.
1.01	4.50	58	.01	0.00	.01	0	1.01	17.20	208	.22	.21	.01	2727.

1.01	4.55	59	.01	0.00	.01	0.	1.01	17.25	209	.22	.21	.01	1216.
1.01	5.00	60	.01	0.00	.01	0.	1.01	17.30	210	.22	.21	.01	1090.
1.01	5.05	61	.01	0.00	.01	0.	1.01	17.35	211	.22	.21	.01	2900.
1.01	5.10	62	.01	0.00	.01	0.	1.01	17.40	212	.22	.21	.01	2850.
1.01	5.15	63	.01	0.00	.01	0.	1.01	17.45	213	.22	.21	.01	2790.
1.01	5.20	64	.01	0.00	.01	0.	1.01	17.50	214	.22	.21	.01	2680.
1.01	5.25	65	.01	0.00	.01	0.	1.01	17.55	215	.22	.21	.01	2620.
1.01	5.30	66	.01	0.01	.01	0.	1.01	18.00	216	.22	.21	.01	2570.
1.01	5.35	67	.01	0.01	.01	0.	1.01	18.05	217	.22	.21	.01	2540.
1.01	5.40	68	.01	0.01	.01	4.	1.01	18.10	218	.22	.21	.01	2510.
1.01	5.45	69	.01	0.01	.01	10.	1.01	18.15	219	.22	.21	.01	2460.
1.01	5.50	70	.01	0.01	.01	20.	1.01	18.20	220	.22	.21	.01	2410.
1.01	5.55	71	.01	0.01	.01	31.	1.01	18.25	221	.22	.21	.01	2360.
1.01	6.00	72	.01	0.01	.01	43.	1.01	18.30	222	.22	.21	.01	1850.
1.01	6.05	73	.01	0.01	.01	53.	1.01	18.35	223	.22	.21	.01	1530.
1.01	6.10	74	.01	0.01	.01	62.	1.01	18.40	224	.22	.21	.01	1230.
1.01	6.15	75	.01	0.01	.01	77.	1.01	18.45	225	.22	.21	.01	960.
1.01	6.20	76	.01	0.01	.01	106.	1.01	18.50	226	.22	.21	.01	770.
1.01	6.25	77	.01	0.01	.01	165.	1.01	18.55	227	.22	.21	.01	620.
1.01	6.30	78	.01	0.01	.01	243.	1.01	19.00	228	.22	.21	.01	510.
1.01	6.35	79	.01	0.01	.01	329.	1.01	19.05	229	.22	.21	.01	420.
1.01	6.40	80	.01	0.01	.01	409.	1.01	19.10	230	.22	.21	.01	350.
1.01	6.45	81	.01	0.01	.01	482.	1.01	19.15	231	.22	.21	.01	310.
1.01	6.50	82	.01	0.01	.01	533.	1.01	19.20	232	.22	.21	.01	270.
1.01	6.55	83	.01	0.01	.01	573.	1.01	19.25	233	.22	.21	.01	240.
1.01	7.00	84	.01	0.01	.01	603.	1.01	19.30	234	.22	.21	.01	220.
1.01	7.05	85	.01	0.01	.01	626.	1.01	19.35	235	.22	.21	.01	210.
1.01	7.10	86	.01	0.01	.01	645.	1.01	19.40	236	.22	.21	.01	190.
1.01	7.15	87	.01	0.01	.01	656.	1.01	19.45	237	.22	.21	.01	180.
1.01	7.20	88	.01	0.01	.01	666.	1.01	19.50	238	.22	.21	.01	160.
1.01	7.25	89	.01	0.01	.01	674.	1.01	19.55	239	.22	.21	.01	170.
1.01	7.30	90	.01	0.01	.01	680.	1.01	20.00	240	.22	.21	.01	170.
1.01	7.35	91	.01	0.01	.01	684.	1.01	20.05	241	.22	.21	.01	160.
1.01	7.40	92	.01	0.01	.01	688.	1.01	20.10	242	.22	.21	.01	160.
1.01	7.45	93	.01	0.01	.01	690.	1.01	20.15	243	.22	.21	.01	160.
1.01	7.50	94	.01	0.01	.01	692.	1.01	20.20	244	.22	.21	.01	160.
1.01	7.55	95	.01	0.01	.01	693.	1.01	20.25	245	.22	.21	.01	160.
1.01	8.00	96	.01	0.01	.01	694.	1.01	20.30	246	.22	.21	.01	160.
1.01	8.05	97	.01	0.01	.01	695.	1.01	20.35	247	.22	.21	.01	160.
1.01	8.10	98	.01	0.01	.01	696.	1.01	20.40	248	.22	.21	.01	160.
1.01	8.15	99	.01	0.01	.01	696.	1.01	20.45	249	.22	.21	.01	160.
1.01	8.20	100	.01	0.01	.01	697.	1.01	20.50	250	.22	.21	.01	160.
1.01	8.25	101	.01	0.01	.01	697.	1.01	20.55	251	.22	.21	.01	160.
1.01	8.30	102	.01	0.01	.01	697.	1.01	21.00	252	.22	.21	.01	160.
1.01	8.35	103	.01	0.01	.01	697.	1.01	21.05	253	.22	.21	.01	160.
1.01	8.40	104	.01	0.01	.01	697.	1.01	21.10	254	.22	.21	.01	160.
1.01	8.45	105	.01	0.01	.01	697.	1.01	21.15	255	.22	.21	.01	160.
1.01	8.50	106	.01	0.01	.01	697.	1.01	21.20	256	.22	.21	.01	160.
1.01	8.55	107	.01	0.01	.01	697.	1.01	21.25	257	.22	.21	.01	160.
1.01	9.00	108	.01	0.01	.01	697.	1.01	21.30	258	.22	.21	.01	160.
1.01	9.05	109	.01	0.01	.01	697.	1.01	21.35	259	.22	.21	.01	160.
1.01	9.10	110	.01	0.01	.01	697.	1.01	21.40	260	.22	.21	.01	160.
1.01	9.15	111	.01	0.01	.01	697.	1.01	21.45	261	.22	.21	.01	160.
1.01	9.20	112	.01	0.01	.01	697.	1.01	21.50	262	.22	.21	.01	160.
1.01	9.25	113	.01	0.01	.01	697.	1.01	21.55	263	.22	.21	.01	160.
1.01	9.30	114	.01	0.01	.01	697.	1.01	22.00	264	.22	.21	.01	160.
1.01	9.35	115	.01	0.01	.01	697.	1.01	22.05	265	.22	.21	.01	160.
1.01	9.40	116	.01	0.01	.01	697.	1.01	22.10	266	.22	.21	.01	160.
1.01	9.45	117	.01	0.01	.01	697.	1.01	22.15	267	.22	.21	.01	160.
1.01	9.50	118	.01	0.01	.01	697.	1.01	22.20	268	.22	.21	.01	160.





COMBINED UPSTREAM ROUTED HYDROGRAPHS  
WITH DOWNSTREAM LOCAL HYDROGRAPHS





AD-A104 828

PRC CONSOER TOWNSEND INC ST LOUIS MO

NATIONAL DAM SAFETY PROGRAM. MEMPHIS RESERVOIR DAM (MO 10163) M--ETC(U)

JAN 79

DACW43-78-C-0160

F/G 13/13

NL

UNCLASSIFIED

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000

END  
DATE  
FILMED  
C 8  
DTIC



SUMMARY OF PMF AND ONE-HALF PMF FLOOD ROUTING

AND  
DAM SAFETY ANALYSIS

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN	RATIO 1	RATIO 2
				1.00	.50
HYDROGRAPH AT	3	3.05	1	24290.	13145.
	(	7.90)	(	744.04)	372.22)
ROUTED TO	3	3.05	1	7445.	2176.
	(	7.90)	(	210.83)	61.62)
HYDROGRAPH AT	14	1.48	1	10971.	5084.
	(	3.83)	(	310.67)	155.34)
2 COMBINED	18	4.53	1	17150.	4571.
	(	11.73)	(	485.64)	146.08)
ROUTED TO	18	4.53	1	15356.	4515.
	(	11.73)	(	434.89)	127.06)

# SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....

RATIO OF BMF	MAXIMUM RESERVOIR W.S. ELEV	ELEVATION STORAGE OUTFLOW	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF	
							MAX OUTFLOW HOURS	FAILURE HOURS
1.00	779.79		0.00	6963.	7405.	0.00	16.83	0.00
.50	776.28		0.00	5873.	2176.	0.00	18.25	0.00

INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
770.00	770.00	780.00
4109.	4109.	7030.
0.	0.	8999.

# SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....

ELEVATION  
STORAGE  
OUTFLOW

INITIAL VALUE  
716.20  
235.  
0.

SPILLWAY CREST  
716.20  
235.  
0.

TOP OF DAM  
720.20  
421.  
2381.

RATIO OF PHF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	724.13	3.93	512.	13358.	9.00	16.33	0.00
.90	721.83	1.23	544.	4515.	3.03	16.58	0.00

